

Test Report


No. : KA/2013/40856 Date : 2013/04/17 Page : 1 of 3

SAN-YE INDUSTRIAL CO.,LTD.
NO.1, LN. 116, GUANGMING RD., WUFENG DIST., TAICHUNG CITY 413,
TAIWAN

The following sample(s) was/were submitted and identified by/on behalf of the client as :

Sample Description : ENGINE PROTECTION OIL
Sample Receiving Date : 2013/04/11
Testing Period : 2013/04/11 TO 2013/04/17
Sample Submitted By : SAN-YE INDUSTRIAL CO.,LTD.

=====
Test Result(s) : Please refer to next page(s).


Ray Chang / Asst. Manager
Signed for and on behalf of
SGS Taiwan Limited



Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.



Test Report

No. : KA/2013/40856 Date : 2013/04/17 Page : 2 of 3

SAN-YE INDUSTRIAL CO.,LTD.
NO.1, LN. 116, GUANGMING RD., WUFENG DIST., TAICHUNG CITY 413,
TAIWAN

Test Result(s)

PART NAME NO.1 : YELLOW ENGINE PROTECTION OIL

PASS

Test Item (s):	Unit	Method	MDL	Result	Limit
				No.1	
ASTM F963-11 (Clause 4.3.5.2) Heavy metal content		With reference to ASTM F963-11 (Clause 4.3.5.2) requirement.			
Lead (Pb)	mg/kg	With reference to CPSC-CH- E1002-08.3 method.	2	n.d.	100
Soluble Antimony (Sb)	mg/kg	With reference to ASTM F963-11 Clause 8.3. Analysis was performed by ICP-AES.	5	n.d.	25
Soluble Arsenic (As)	mg/kg		2.5	n.d.	1000
Soluble Barium (Ba)	mg/kg		10	n.d.	75
Soluble Cadmium (Cd)	mg/kg		5	n.d.	60
Soluble Chromium (Cr)	mg/kg		5	n.d.	90
Soluble Lead (Pb)	mg/kg		5	n.d.	60
Soluble Mercury (Hg)	mg/kg		5	n.d.	60
Soluble Selenium (Se)	mg/kg		5	n.d.	500

- Note : 1. mg/kg = ppm ; 0.1wt% = 1000ppm
 2. n.d. = Not Detected
 3. MDL = Method Detection Limit

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。
 This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

SGS Taiwan Ltd.
 台灣檢驗科技股份有限公司

No. 61, Kai-Fa Road, Nanzih Export Processing Zone, Kaohsiung, Taiwan /
 t + 886 (07)301 2121

高雄市楠梓加工出口區開發路61號
 f + 886 (07)3010867
www.tw.sgs.com

Member of the SGS Group

Test Report

No. : KA/2013/40856 Date : 2013/04/17 Page : 3 of 3

SAN-YE INDUSTRIAL CO.,LTD.
NO.1, LN. 116, GUANGMING RD., WUFENG DIST., TAICHUNG CITY 413,
TAIWAN

* The tested sample / part is marked by an arrow if it's shown on the photo. *

KA/2013/40856



** End of Report **

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested. This test report cannot be reproduced, except in full, without prior written permission of the Company. 除非另有說明，此報告結果僅對測試之樣品負責。本報告未經本公司書面許可，不可部分複製。
This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.